

# **VEHICLE INSPECTION REPORT**

PF70UOU

## Fiat Ducato 35 MAXI 2.3 MULTIJET 140PS

**Vehicle** 

| Serious Damage? | No                        | VAT         | Plus VAT          |           |           |
|-----------------|---------------------------|-------------|-------------------|-----------|-----------|
|                 |                           | V5          | Present           | -         |           |
| Details         |                           |             |                   |           |           |
| Reg. date       | 12/02/2021                | VIN         | ZFA25000002P45276 | CAP Below | £4,500.00 |
| Year            | 2021                      | Body Style  | Dropside          | Gearbox   | MANUAL    |
| Mileage         | 76,311 Miles<br>Warranted | MOT Due     | 11/02/2026        | Gears     | 6         |
|                 |                           | _ CAP Clean | £5,925.00         | Tail Lift | Column    |
| Fuel Type       | Diesel                    | CAP Average | £5,375.00         |           |           |
| Colour          | MULTI-COLOURED            |             |                   | -         |           |

#### AD-BLUE, TOW BAR, E/ MIRRORS

| ı | yres |
|---|------|
| _ |      |

Inspection

NSF

NSR

OSF

**OSR** 

**Spare** 

### **Features**

- · Bluetooth connection
- · Front electric windows · Cloth seat trim
- · Park assist camera
- · Drivers airbag
- Digital radio
- Passenger airbag
- · Air conditioning
- Central locking

#### **Photos**














**Commercial Vehicle Auctions Limited** 



# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Moulding Scuffed (Unpainted) Over 100mm



3: Wing nsf Scratched Over 25mm Thru Paint



4: Door Mirror Assy nsf Broken Replace



5: Door osf Dented With Paint Damage



6: Door Mirror Glass os Broken Replace



7: Door Mirror Assy osf Broken Replace



8: Wing osf Dented With Paint Damage



9: Bumper Front Moulding Scuffed (Unpainted) Over 100mm



10: Carpets Front Holed Over 3mm



11: Seat Base Cover nsf Soiled Heavy

### Interior

| Carpet Condition Seat Condition | Poor<br>Poor |    | Upholstery Condition Odour | OK<br>No |    |
|---------------------------------|--------------|----|----------------------------|----------|----|
| Engine Runs                     |              | OK | No Excessive Smoking       |          | OK |
| EML light illuminated           |              | OK | C DPF light illuminated    |          | OK |
| ABS light illuminated           |              | OK |                            |          |    |