

# VEHICLE INSPECTION REPORT

**LN16NXV**

## Daf LF 220

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 03/03/2016

Year 2016

Mileage 386,663 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour WHITE

VIN XLRAEL3700L450199

Body Style Skiploader

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

\*WARNING LIGHTS ON DASH\* HYVALIFT NG2012XL GEAR (YEAR 2015), SHEETING SYSTEM

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4


## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Cracked  
Replace

2: Bonnet  
Scratched  
UpTo 25mm Thru Paint



3: Number Plate Front  
Broken  
Replace

4: Bumper Front  
Rusted  
Over 5mm



5: Bumper Front  
Dented  
Between 10mm + 30mm

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Dented  
With Paint Damage

8: Door nsf  
Dented  
With Paint Damage



9: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



12: Qtr Panel osr  
Dented  
With Paint Damage



13: Door osf  
Chipped  
Edge Chip



14: Door Mirror Assy osf  
Broken  
Replace



15: A Post os  
Scratched  
UpTo 25mm Thru Paint

16: Seat Base Cover osf  
Holed  
Over 3mm



17: Switches And Controls  
Broken  
Replace

Interior

| Carpet Condition         | Average |  | Upholstery Condition                           | Average |
|--------------------------|---------|--|------------------------------------------------|---------|
| Seat Condition           | Average |  | Odour                                          | -       |
| Engine Runs              | OK      |  | Gearbox 1st and Reverse Test                   | OK      |
| Brakes                   | OK      |  | Clutch Slip Test from Static                   | OK      |
| Parking Brake            | OK      |  | Gearbox Static Gear Selection (engine running) | OK      |
|                          |         |  | No Excessive Smoking                           | OK      |
| EML light illuminated    | Fault   |  | Oil warning light illuminated                  | OK      |
| Airbag light illuminated | OK      |  | DPF light illuminated                          | OK      |
| ABS light illuminated    | Fault   |  | Service indicator light illuminated            | OK      |