

VEHICLE INSPECTION REPORT

C327453

MONTRACON FRIDGE BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	Colour	Axle Combi	Tri
Year	VIN	SMRR3ACXBN101918	Rear Doors
Mileage	TBC	Body Style	Trailer
Fuel Type	Brakes	Disc	

CARRIER VECTOR 1550 UNIT, MERC AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



