

VEHICLE INSPECTION REPORT

FP68AVD

Vauxhall Vivaro 2700 1.6 CDTI 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/10/2018

Year 2018

Mileage 47,899 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W0VF7F607KV613292

Body Style Panel Van L1

MOT Due Expired

CAP Clean £6,000.00

CAP Average £5,200.00

CAP Below £4,075.00

Gearbox MANUAL

Gears 6

WARNING LIGHTS ON DASH, POWER STEERING ISSUES, ONLY RUNS WITH JUMP PACK ATTACHED
SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Bonnet
Chipped
Multiple Chips



5: Other
N/A
N/A



6: Door nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door osr
Dented
Over 2 UpTo 10mm



14: Door osr
Dented
Over 2 UpTo 10mm



15: Door osr
Dented
Between 10mm + 30mm



16: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



19: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault